



铅、镉空芯阴

铅、镉元素检测的重要性

铅 镉暴露



仪器

AAS-S200 40μl 360μl 1.5min 20232220572

试剂

() 0.36mLx200 / 1.0gX6 / 20222400130

铅、镉对人体的损害



- 1 ()
- ()

0.5gX3 (1 2 4);
0.5gx3 (3 5 6);
0.5gX6 (1);
0.5gX6 (2);